



ADI (Analog Devices, Inc.)

AD9517-4ABCPZ-RL7

Numero ng Bahagi:

AD9517-4ABCPZ-RL7

Tagagawa / Brand:

ADI (Analog Devices, Inc.)

Paglalarawan ng produkto

IC CLOCK GEN 1.8GHZ VCO 48LFCSP

Mga Datasheet:

 AD9517-4ABCPZ-RL7.pdf

Katayuan ng RoHS

 Lead free / RoHS Compliant

Stock Kondisyon

8639 pcs stock

Ipadala Mula

Hong Kong


Pagpapadala ng Way

DHL/Fedex/TNT/UPS/EMS



Ang imahe ay maaaring representasyon. Tingnan ang mga pagtutukoy para sa mga detalye ng produkto.













Mga pagtutukoy ng AD9517-4ABCPZ-RL7

NUMERO NG BAHAGI	AD9517-4ABCPZ-RL7
MANUFACTURER	ADI (Analog Devices, Inc.)
PAGLALARAWAN	IC CLOCK GEN 1.8GHZ VCO 48LFCSP
LEAD FREE STATUS / KATAYUAN NG ROHS	Lead free / RoHS Compliant
AVAILABLE ANG DAMI	8639 pcs
DATA SHEET	 AD9517-4ABCPZ-RL7.pdf
BOLTAHE - SUPPLY	3.135 V ~ 3.465 V
URI	Clock Generator, Fanout Distribution
SUPPLIER APARATO PACKAGE	48-LFCSP-VQ (7x7)
SERYE	-
RATIO - INPUT: OUTPUT	1:12
PACKAGING	Tape & Reel (TR)
PACKAGE / KASO	48-VFQFN Exposed Pad, CSP
PLL	Yes
OUTPUT	CMOS, LVDS, LVPECL
IBANG PANGALAN	AD9517-4ABCPZ-RL7-ND AD9517-4ABCPZ-RL7TR
OPERATING TEMPERATURE	-40°C ~ 85°C
BILANG NG CIRCUITS	1
SALALAYAN TYPE	Surface Mount
ANG SENSITIVITY LEVEL (MSL)	3 (168 Hours)
LEAD LIBRENG STATUS / KATAYUAN NG ROHS	Lead free / RoHS Compliant
INPUT	CMOS, LVDS, LVPECL
FREQUENCY - MAX	1.8GHz
DIVIDER / MULTIPLIER	Yes/No
DIFFERENTIAL - INPUT: OUTPUT	Yes/Yes
NUMERO NG BASE BAHAGI	AD9517

Kaugnay na Mga Tag

ADI (Analog Devices, Inc.) AD9517-4ABCPZ-RL7	AD9517-4ABCPZ-RL7 Distributor	AD9517-4ABCPZ-RL7 Supplier
AD9517-4ABCPZ-RL7 Presyo	AD9517-4ABCPZ-RL7 Pictures	AD9517-4ABCPZ-RL7 Image
AD9517-4ABCPZ-RL7 PDF Datasheet	AD9517-4ABCPZ-RL7 I-download ang Datasheet	AD9517-4ABCPZ-RL7 Datasheet
AD9517-4ABCPZ-RL7 Stock	Bumili ng AD9517-4ABCPZ-RL7	Bumili ADI (Analog Devices, Inc.) AD9517-4ABCPZ-RL7
ADI (Analog Devices, Inc.) AD9517-4ABCPZ-RL7	ADI (Analog Devices, Inc.) Supplier	ADI (Analog Devices, Inc.) Distributor
ADI (Analog Devices, Inc.) AD9517-4ABCPZ-RL7	AD AD9517-4ABCPZ-RL7	ADI (Analog Devices, Inc.) AD9517-4ABCPZ-RL7
Analog Devices Inc. AD9517-4ABCPZ-RL7	Analog Devices, Inc. AD9517-4ABCPZ-RL7	

Kaugnay na Mga Produkto

 <p>AD9517-3A/PCBZ Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: BOARD EVALUATION FOR AD9517-3A Sa stock: 412 pcs</p> <p>RFQ</p>	 <p>AD9517-3ABCPZ Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: IC CLOCK GEN 2.0GHZ VCO 48LFCSP Sa stock: 7376 pcs</p> <p>RFQ</p>
 <p>AD9517-4A/PCBZ Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: BOARD EVALUATION FOR AD9517-4A Sa stock: 484 pcs</p> <p>RFQ</p>	 <p>AD9518-0ABCPZ Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: IC CLOCK GEN 6CH 2.8GHZ 48LFCSP Sa stock: 6596 pcs</p> <p>RFQ</p>
 <p>AD9517-3ABCPZ-RL7 Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: IC CLOCK GEN 2.0GHZ VCO 48LFCSP Sa stock: 10320 pcs</p> <p>RFQ</p>	 <p>AD9518-0ABCPZ-RL7 Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: IC CLOCK GEN 6CH 2.8GHZ 48LFCSP Sa stock: 11316 pcs</p> <p>RFQ</p>
 <p>AD9517-2ABCPZ-RL7 Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: IC CLOCK GEN 2.2GHZ VCO 48LFCSP Sa stock: 9751 pcs</p> <p>RFQ</p>	 <p>AD9518-0A/PCBZ Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: BOARD EVALUATION FOR AD9518-0A Sa stock: 384 pcs</p> <p>RFQ</p>
 <p>AD9518-1ABCPZ Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: IC CLOCK GEN 6CH 2.65GHZ 48LFCSP Sa stock: 6824 pcs</p> <p>RFQ</p>	 <p>AD9518-1A/PCBZ Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: BOARD EVALUATION FOR AD9518-1A Sa stock: 457 pcs</p> <p>RFQ</p>
 <p>AD9518-1ABCPZ-RL7 Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: IC CLOCK GEN 6CH 2.65GHZ 48LFCSP Sa stock: 9366 pcs</p> <p>RFQ</p>	 <p>AD9517-4ABCPZ Mga Tagagawa: ADI (Analog Devices, Inc.) Paglalarawan: IC CLOCK GEN 1.8GHZ VCO 48LFCSP Sa stock: 5649 pcs</p> <p>RFQ</p>